Shaw® a world of Solutions™

312 Directors Drive
Knoxville, Tennessee 37923
865.690.3211
FAX: 865.690.3626

October 18, 2012

U.S. Army Engineer District, Nashville
ATTN: CELRN-EC-E (Ms. Kathy McClanahan)
110 Ninth Avenue South, Room 682
U.S. Court House Annex
Nashville, Tennessee 37203

Submittal of the Final Ash Pit No. 1 and Ash Pit No. 3
Site Characterization Report Addendum for Coal Yard No. 1
Former Plum Brook Ordnance Works, Sandusky, Ohio
Contract No. W912QR-08-D-0013: Shaw Project Number 132457

Dear Ms. McClanahan:

In accordance with the requirements of Delivery Order No. DX02 of Contract No. W912QR-08-D-0013, Shaw is pleased to submit this Final Ash Pit No. 1 and Ash Pit No. 3 Site Characterization Report Addendum for Coal Yard No. 1 at the Former Plum Brook Ordnance Works (PBOW) located in Sandusky, Ohio.

Enclosed are four copies of this final report. Copies have also been sent to those on the distribution list, as indicated. As requested, the document was sent to the Center of Expertise and RAB in electronic format only.

Should you have any questions or require additional information regarding this submittal, please do not hesitate to contact me at (865) 694-7496.

Sincerely,

Steven T. Downey, PE, PMP
Project Manager

Enclosures

G05OH001821_01.01_1013_a

Control Copy Distribution List

Name	Control Copy
U.S. Army Engineer District, Nashville ATTN: CELRN-EC-E (Ms. Kathy McClanahan) 110 Ninth Avenue South, Room 682 Annex Nashville, TN 37203	1-4
U.S. Army Engineer District, Huntington ATTN: CELRH-PM-PP-P (Mr. Rick Meadows) 502 Eighth Street Huntington, West Virginia 25701-2070	5-7
Mr. Paul Jayko Site Coordinator Division of Emergency and Remedial Response (DERR) Ohio Environmental Protection Agency 347 North Dunbridge Road Bowling Green, Ohio 43402-0466	8, 9
Janusz Z. Byczkowski Ohio Environmental Protection Agency Div. Emergency and Remedial Response Central Office Lazarus Government Ctr. 50 W. Town Str., Suite 700 Columbus, Ohio 43216-1049	10
Mr. Robert Lallier Environmental Coordinator NASA - Plum Brook Station 6100 Columbus Avenue Sandusky, Ohio 44870	11
Mr. John Blakeman PBOW RAB acting Co-chairman 2412 Scheid Road Huron, Ohio 44839	(CD only)
Mr. Jeffrey G. Leach U.S. Army Public Health Command ATTN: MCHB-IP-REH, Bldg. 1675 APG-EA, MD 21010-5403	12

Shaw® a world of Solutions™

DISCIPLINE SIGN-OFF REVIEW

Client Name: U.S. Army Engineer District, Nashville; CELRN-EC-E

Project Description: Ash Pit No. 1 and Ash Pit No. 3 Site Characterization Report Addendum for Coal Yard No. 1
Former Plum Brook Ordnance Works, Sandusky, Ohio

Contract No. W912QR-08-D-0013 Delivery Order No. DX02

Project No. 132457 Task/Phase Number: 41000000

Document Type	Identify specific section or segment covered by this checkprint	Document Origin
☐ Technical / Cost Proposal		X Originator Developed
☐ RFP		☐ Edited Standard
☐ Contract / Subcontract		☐ Client Furnished
☐ Work Plans		
X Report	Site Characterization Report Addendum	**Document Status**
☐ Risk Assessment / Evaluation		☐ Preliminary
☐ Specifications & Plans		☐ Internal Draft
☐ Design Calculations		☐ Draft
☐ Tables		☐ Draft Final
☐ Drawings / Figures		X Final
☐ Other:		☐ Other:

	Required Person	Signature	Date
Originator	David Kessler	David Kessler	10-18-12
Editor	Donald Groseclose	Don Groseclose	10-18-12
Peer Review	Eric Weaver	David Kessler for	10-18-12
Technical Review	Michael Gunderson	[illegible]	10-18-12
Technical Review	Tom Siard	[illegible]	10-18-12
Quality Assurance Mgr	Ken Martinez	[illegible]	10-18-12
Project Manager	Steven Downey	Steven Downey	10/18/12

NOTICE: By signature above, parties certify that the subject document has been prepared by and/or reviewed by them (as appropriate), that all review comments have been resolved, and that the document is ready for submittal.