Shaw® a world of Solutions™

312 Directors Drive
Knoxville, Tennessee 37923
865.690.3211
FAX: 865.690.3626

June 13, 2011

U.S. Army Engineer District, Nashville
ATTN: CELRN-EC-E (Ms. Kathy McClanahan)
110 Ninth Avenue South, Room 682
U.S. Court House Annex
Nashville, Tennessee 37203

Submittal of the Final Site-Specific Sampling and Analysis Plan Remedial Investigation for Data Gap Investigation for the Garage Maintenance Area- Former Sellite Area and Unloading Area
Former Plum Brook Ordnance Works, Sandusky, Ohio
Contract No. W91278-10-D-0094: Shaw Project No. 141427

Dear Ms. McClanahan:

In accordance with the requirements of Delivery Order No. DX01 of Contract No. W91278-10-D-0094, Shaw is pleased to submit the Final Site-Specific Sampling and Analysis Plan Remedial Investigation for the Data Gap Investigation for the Garage Maintenance Area- Former Sellite Area and Unloading Area at the Former Plum Brook Ordnance Works (PBOW) located in Sandusky, Ohio.

Enclosed are three copies of this final report. Copies have also been sent to those on the distribution list, as indicated, for their records. As requested, the document was sent to the Center of Expertise and RAB in electronic format only.

Should you have any questions or require additional information regarding this submittal, please do not hesitate to contact me at (865) 694-7496.

Sincerely,

Steven T. Downey, PE, PMP
Project Manager

Enclosures

Control Copy Distribution List

Name	Control Copy
U.S. Army Engineer District, Nashville ATTN: CELRN-EC-E (Ms. Kathy McClanahan) 110 Ninth Avenue South, Room 682 Annex Nashville, TN 37203	1-3
U.S. Army Engineer District, Huntington ATTN: CELRH-PM-PP-P (Mr. Rick Meadows) 502 Eighth Street Huntington, West Virginia 25701-2070	4-6
Mr. Paul Jayko Site Coordinator Division of Emergency and Remedial Response (DERR) Ohio Environmental Protection Agency 347 North Dunbridge Road Bowling Green, Ohio 43402-0466	7, 8
Janusz Z. Byczkowski Ohio Environmental Protection Agency Div. Emergency and Remedial Response Central Office Lazarus Government Ctr. P.O. Box 1049 50 W. Town Str., Suite 700 Columbus, Ohio 43216-1049	9
Mr. Robert Lallier Environmental Coordinator NASA - Plum Brook Station 6100 Columbus Avenue Sandusky, Ohio 44870	10
U.S. Army Corps of Engineers HTRW Center of Expertise ATTN: CEHNC-CX-EG (Vern StJohn) 1616 Capitol Avenue Omaha, Nebraska 68144-3869	(CD only)
Mr. John Blakeman PBOW RAB Co-Chairperson 2412 Scheid Road Huron, Ohio 44846	(CD only)

Shaw® a world of Solutions™

DISCIPLINE SIGN-OFF REVIEW

Client Name: U.S. Army Engineer District, Nashville; CELRN-EC-R

Project Description: Work Plan RI Data Gap Investigation for the Garage Maintenance Area- Former Sellite Area and Unloading Area Former Plum Brook Ordnance Works, Sandusky, Ohio

Contract No. W 9 1 2 7 8 - 1 0 - D - 0 0 9 4

Delivery Order No. D X 0 1

Project No. 1 4 1 4 2 7

Task/Phase Number: 0 2 0 0 0 0 0 0

Document Type	Identify specific section or segment covered by this checkprint	Document Origin
☐ Technical / Cost Proposal		X Originator Developed
☐ RFP		☐ Edited Standard
☐ Contract / Subcontract		☐ Client Furnished
X Work Plans		
☐ Report		**Document Status**
☐ Risk Assessment / Evaluation		☐ Preliminary
☐ Specifications & Plans		☐ Internal Draft
☐ Design Calculations		☐ Draft
☐ Tables		☐ Draft Final
☐ Drawings / Figures		X Final
☐ Other:		☐ Other:

	Required Person	Signature	Date
Originator	Jonathan Reagan		6/13/11
Editor	Donald Groseclose		6-13-11
Peer Review	Eric Weaver	for E. Weaver	6/13/11
Technical Review	Michael Gunderson		6/13/11
Technical Review	Tom Siard		6/13/11
Quality Assurance Mgr	Ken Martinez		06-13-11
Project Manager	Steven Downey	for S. Downey	6/13/11

NOTICE: By signature above, parties certify that the subject document has been prepared by and/or reviewed by them (as appropriate), that all review comments have been resolved, and that the document is ready for submittal.